



**Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road SE, Tumwater WA 98501**

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

School Name: Catherine Blaine Elementary

School Code: 2838

School District Name: Seattle

Address: 2550 34th Ave W, Seattle WA 98199

County: King

Number of Samples Collected: 33

Date Collected: 06/05/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	10575	First Draw	Tap	Kitchen middle sink	3	6/09/2018	7:00 AM, 17 on school map
2.	10576	First Draw	Bubbler	Upper floor drinking fountain behind cafeteria	<1	6/09/2018	Left Side Drinking Fountain, 12 on school map
3.	10581	First Draw	Bubbler	Upper Floor Drinking Fountain behind Cafeteria	<1	6/09/2018	Right Side Drinking Fountain, 05 on school map
4.	10583	First Draw	Tap	Room 140 A	<1	6/09/2018	23 on school map
5.	10584	First Draw	Tap	Room 140 B	2	6/09/2018	32 on school map
6.	10585	First Draw	Tap	Room 139 A	TB		22 on school map
7.	10586	First Draw	Tap	Room 139B	2	6/09/2018	31 on school map
8.	10587	First Draw	Bubbler	By Room 137	<1	6/09/2018	02 on school map
9.	10588	First Draw	Tap	Room 137	8	6/09/2018	29 on school map
10.	10589	First Draw	Tap	Room 136	1	6/09/2018	33 on school map
11.	10590	First Draw	Tap	Room 135	TB		Touched bottles mouth to tap, 34 on school map

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
12.	10591	First Draw	Tap	Room 134B	TB		28 on school map
13.	10592	First Draw	Tap	Room 134A	TB		27 on school map
14.	10593	First Draw	Tap	Room 133B	TB		35 on school map
15.	10594	First Draw	Tap	Room 133A	TB		36 on school map
16.	10595	First Draw	Tap	Room 127	<1	6/09/2018	37 on school map
17.	10596	First Draw	Bubbler	By Girls Restrooms Near 127	<1	6/09/2018	Left Side Drinking Fountain, 03 on map
18.	10597	First Draw	Bottle Filler	By Girls Restrooms Near 133A	<1	6/09/2018	Right Side, 13 on Map
19.	10598	First Draw	Bubbler	By Room 141	TB		04 on map
20.	10599	First Draw	Tap	Left Most Sink Room 141	2	6/09/2018	Not on map
21.	10600	First Draw	Tap	Middle Sink Room 141	<1	6/09/2018	Not on map
22.	10601	First Draw	Tap	Middle Sink Room 142	3	6/09/2018	Not on map
23.	10602	First Draw	Tap	Right most Sink in Room 142	9	6/09/2018	Not on map

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
24.	10603	First Draw	Bubbler	By Room 122	7	6/09/2018	06 on map
25.	10604	First Draw	Tap	Office Workroom	2	6/09/2018	26 on map
26.	10605	First Draw	Tap	Office Across from Workroom	1	6/09/2018	25 on map
27.	10606	First Draw	Tap	Nurses Room	<1	6/09/2018	15 on map
28.	10607	First Draw	Bubbler	By Room 105 A	<1	6/09/2018	07 on map
29.	10608	First Draw	Bubbler	Outside gym	<1	6/09/2018	10 on map
30.	10609	First Draw	Bubbler	Outside gym	<1	6/09/2018	11 on map
31.	10610	First Draw	Bubbler	Inside gym near boys room	7	6/09/2018	09 on school map
32.	10611	First Draw	Bubbler	Inside gym near girls room	<1	6/09/2018	08 on school map
33.	10613	Blank	Blank	Near entrance	<1	6/09/2018	03404

TB- Turbidity, further analysis required.